ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0125, W0135, W0131, W0126, W0171, W0165, W0128, W	Veera Anjaneya Temple Rd, NA, 1st Crs, Vinayaka Lyt 4th Crs	Jakkur Layout
Segment No.	**Total Length (m)**	
7/C-W0125/S115358	459.93	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	103.01	77.599217	13.072765	77.599015	13.071855	7th Cross	Main Road
2	164.76	77.598693	13.071818	77.598264	13.070392	8th B Cross	Daed End
3	91.80	77.598706	13.071935	77.598882	13.072746	9th B Cross	Dead End
4	100.36	77.598024	13.071806	77.598226	13.072691	9th A Cross	Main Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads of 12th to 18th Cross right side of Jakkur Layout in Ward No 07, Byatarayanapura	4850000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Road	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1.Providing and laying Asphalt to roads.	007-18-000046
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/102/17-18	02/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
19/05/2020	18/05/2023	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00
Phone No.	**E-Mail ID**	
9900333496		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
10/06/2020		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0125, W0135, W0131, W0126,

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	03/07/2020	18/06/2020	As proposed
SE	Vijay Kumar Haridas	11/06/2020	18/06/2020	Forwarded
EE	Mohandas H.T	11/06/2020	18/06/2020	Verified
AEE	H.Ranganath	11/06/2020	18/06/2020	Verified
AE	Pushpalatha.N.D	10/06/2020	18/06/2020	Mobile Verification Done
AE	Pushpalatha.N.D	19/05/2020	18/06/2020	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0125, W0135, W0131, W0126,